ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ID PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
		315290	B. WING			4/23/2021
AME OF PF	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CO	ODE	
UCKING	HAM AT NORWOOD, TH	IE		100 MCCLELLAN STREET NORWOOD, NJ 07648		
(X4) ID		TATEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF ((X5)
PREFIX TAG		Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTI CROSS-REFERENCED TO TI DEFICIENC	HE APPROPRIATE	DATE
E 000	Initial Comments		E 0	00		
	Appendix Z-Emerger Provider and Supplie	equirements for Long Term				
K 000	INITIAL COMMENTS	3	K 0	00		
	New Jersey Departm Survey and Field Op Buckingham at Norw noncompliance with participation in Media 483.90(a), Life Safet Edition of the Nationa	care/Medicaid at 42 CFR y from Fire, and the 2012 al Fire Protection Association ety Code (LSC), Chapter 19				
K 222 SS=D	that was built in 80's construction. The fac smoke zones.	Norwood is a 3 story building It is composed of Type II ility is divided into multiple	K 2	22		5/7/21
	equipped with a latch use of a tool or key fi using one of the follo arrangements: CLINICAL NEEDS O LOCKING	neans of egress shall not be n or a lock that requires the rom the egress side unless wing special locking R SECURITY THREAT g arrangements for the				

Electronically Signed

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

05/07/2021

	S FOR MEDICARE &					NO. 0938-03
ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ID PLAN OF CORRECTION IDENTIFICATION NUMBER:		. ,	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		TE SURVEY MPLETED	
		315290	B. WING		0	4/23/2021
NAME OF PI	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CO	DE	
BUCKING	HAM AT NORWOOD, TH	E		100 MCCLELLAN STREET NORWOOD, NJ 07648		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	N SHOULD BE E APPROPRIATE	(X5) COMPLETIC DATE
K 222	Continued From page	• 1	K 2	22		
	locks; keying of all loc all times; or other suc to the staff at all times 18.2.2.2.5.1, 18.2.2.2 SPECIAL NEEDS LO Where special locking safety needs of the pa Clinical or Security Lo being met. In addition electrical locks that fa upon loss of power to protected by a superv system and the locked complete smoke dete constantly monitored within the locked space and detection system doors upon activation 18.2.2.2.5.2, 19.2.2.2 DELAYED-EGRESS ARRANGEMENTS Approved, listed delay installed in accordance permitted on door ass ordinary hazard contect throughout by an app fire detection system automatic sprinkler sy 18.2.2.2.4, 19.2.2.2.4	.6, 19.2.2.2.5.1, 19.2.2.2.6 CKING ARRANGEMENTS g arrangements for the atient are used, all of the bocking requirements are a, the locks must be ill safely so as to release the device; the building is vised automatic sprinkler d space is protected by a ction system (or is at an attended location ce); and both the sprinkler s are arranged to unlock the .5.2, TIA 12-4 LOCKING yed-egress locking systems ce with 7.2.1.6.1 shall be semblies serving low and ents in buildings protected roved, supervised automatic or an approved, supervised ystem.				

Facility ID: NJ60232

If continuation sheet Page 2 of 8

	OF DEFICIENCIES				(X3) DATE	0. 0938-039
	F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		COMPLETED	
	315290		B. WING		04/	23/2021
NAME OF P	AME OF PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE		
BUCKING	HAM AT NORWOOD, TH	E		100 MCCLELLAN STREET NORWOOD, NJ 07648		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	D BE	(X5) COMPLETIO DATE
K 222	Continued From page	e 2	K 22	2		
	door assemblies in bi by an approved, supe detection system and automatic sprinkler si 18.2.2.2.4, 19.2.2.2.4 This REQUIREMENT by: Based on observation review on 4/13/21, it facility failed to comp locking requirements 7.2.1.6.1 as evidence During a tour of the presence of the facilit 1:00 PM, the surveyor doors locked with a di failed to open when the The exit door at the ere was engaged by app Also, the delayed-egin a coded keypad. The the code was inputted Director. This finding Maintenance Director	1.6.3 shall be permitted on uildings protected throughout ervised automatic fire I an approved, supervised ystem. T is not met as evidenced on, interview and record was determined that the ly with the exit door special of NFPA 101:2012 - ed by the following: Unit in the ty's Maintenance Director at or observed one of two exit lelayed-egress lock that ested. Unot open within 15-30 lease mechanism (push-bar) lying continuous pressure. ress lock was equipped with e lock failed to release when d by the Maintenance		HOW THE CORRECTIVE ACTION BE ACCOMPLISHED: The Egress door at the end of the hallway failed to release after delay egress test. POC : On 4/13/21 the faulty wire connection between the wander gua and the door was repaired by the maintenance director. MONITORING The Maintenance Director or desig will round daily and check the wand guard system and the egress doors facility. The Rounds will be tracked by maintenance and reported to the maintenance Director and QAPI	ved ard nee er	
	caused by a faulty co wanderguard system resolved. A review of the facility	failure to release was		committee Quarterly X 1 YR.		

If continuation sheet Page 3 of 8

CENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA		(X2) MULTIP	LE CONSTRUCTION	OMB NO. 0938-03 (X3) DATE SURVEY	
ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	COMPLETED		
		315290	B. WING		04/23/2021
NAME OF PROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE	
BUCKING	HAM AT NORWOOD, TH	E		100 MCCLELLAN STREET NORWOOD, NJ 07648	
		ATEMENT OF DEFICIENCIES	ID	PROVIDER'S PLAN OF CORRECTION	ON (X5)
(X4) ID PREFIX TAG	(EACH DEFICIENC	Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	PREFIX TAG	(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE COMPLETIO
K 222	Continued From page	e 3	K 22	2	
	were routinely checked 04/01/21.	ed and was last done on			
		/ informed the facility's inding during the Life Safety a 2:45 PM			
1/ 701	NJAC-8:39-31.2(e) NFPA 101:2012 7.2.1		K 79	1	E/0E/04
SS=D	Portable Space Heat CFR(s): NFPA 101	ers	K 78		5/25/21
	unless used in nonsle areas where the heat 212 degrees Fahrenh 18.7.8, 19.7.8				
	Based on observation it was determined that	n and interview on 4/13/21, at the facility failed to prohibit bace heaters in resident		HOW THE CORRECTIVE ACTION BE ACCOMPLISHED:	WILL
	sleeping areas.			A PORTABLE Space heater was fou social services on floor.	und in
	following finding:	e was is evidenced by the		POC : on 4/13/21 Space heater was removed immediately from the office	e.
	presence of the facilit portable heater in the located on the flow was not on at the time This finding was verif	eyor observed, in the ty's Maintenance Director, a social Services office or nurses unit. The heater e of surveyor's observation. ied by the Maintenance		On 5/3/21 Education was provided t department heads and staff membe regarding the NO USAGE of space heaters at anytime in the building by maintenance Director.	rs
	who immediately rem	ew during the observation loved both items.		HOW FACILITY WILL MONITOR	

Event ID: Y4GD21

Facility ID: NJ60232

If continuation sheet Page 4 of 8

					OMB NO. 0938-0	
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		COMPLETED	
		315290	B. WING		04/23/2021	
NAME OF P	AME OF PROVIDER OR SUPPLIER		:	STREET ADDRESS, CITY, STATE, ZIP CODE		
BUCKINGHAM AT NORWOOD, THE						
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE COMPLET	
K 781	The surveyor verbally	v informed the facility's inding during the Life Safety at 2:45 PM.	K 781	All space heaters were removed from building by the maintenance director 4/14/21. The maintenance Director C Designee will round weekly to identify there are no space heaters in the fac This will be done by the maintenance director or designee and results repo to the Administrator and QAPI comm X4 Quarters. Maintenance Director or Designee w report to the Quarterly QAPI Commit 4 Quarters.	on vr / that ility. e rted ittee ill	
K 920 SS=D	CFR(s): NFPA 101 Electrical Equipment Extension Cords Power strips in a pati- used for components patient-care-related e (PCREE) assembles by qualified personne 10.2.3.6. Power strip may not be used for r electronics), except in rooms that do not use PCREE meet UL 136 strips for non-PCREE (outside of vicinity) m care rooms, power st standards. All power precautions. Extensi substitute for fixed wi Extension cords used immediately upon con	ent care vicinity are only of movable electrical equipment that have been assembled el and meet the conditions of is in the patient care vicinity non-PCREE (e.g., personal n long-term care resident e PCREE. Power strips for 3A or UL 60601-1. Power in the patient care rooms eet UL 1363. In non-patient rips meet other UL strips are used with general on cords are not used as a	К 920		5/7/21	

Facility ID: NJ60232

If continuation sheet Page 5 of 8

		ID HUMAN SERVICES MEDICAID SERVICES			FO	ED: 11/09/202 RM APPROVE NO. 0938-039
STATEMENT (DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			TE SURVEY MPLETED
		315290	B. WING			04/23/2021
NAME OF PI	ROVIDER OR SUPPLIER	I		STREET ADDRESS, CITY, STATE, ZIP CODE		
BUCKING	HAM AT NORWOOD, TH	F		100 MCCLELLAN STREET		
2001010		-		NORWOOD, NJ 07648		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION SI CROSS-REFERENCED TO THE AF DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
K 920	Continued From page	e 5	K 9	20		
	(NFPA 70), 590.3(D) This REQUIREMENT by:	I0.2.4 (NFPA 99), 400-8 (NFPA 70), TIA 12-5 ⁻ is not met as evidenced n and interview on 4/13/21,		HOW THE CORRECTIVE ACT	ION WILL	
	it was determined that	It the facility failed to prohibit JL rated power strips in the		BE ACCOMPLISHED A NON-UL listed power cord for		
	This deficient practice	e was is evidenced by the		fl social services office.		
	following finding: At 12:15 PM the surv presence of the facilit unprotected electrica standard wall outlet. 1363 rated and was u extension to power a Services office locate unit. This finding was Director in an intervie and who immediately The surveyor verbally	eyor observed, in the cy's Maintenance Director, a l power strip plugged into a This device was not UL used as an electrical portable heater in the Social d on the 2nd floor nurses s verified by the Maintenance w during the observation		on 4/13/21 The power cord was by the maintenance Director On 4/13/21 in-service was prese staff regarding non usage of ext cords except 1363 UL which is a be used in the facility. HOW WILL MONITOR WEEKLY rounds will be conduct maintenance team or designee reported to QAPI Committee for Quarters.	ented to all rension allowed to ted by the and will be	
K 923	Code exit conference NJAC 8:39-31.2(e) NFPA 101:2012 - 19. Gas Equipment - Cyli	at 2:45 PM.	К 9	23		5/19/21
SS=D	Gas Equipment - Cyli Greater than or equa Storage locations are	designed, constructed, and nce with 5.1.3.3.2 and				

Facility ID: NJ60232

If continuation sheet Page 6 of 8

	S FOR MEDICARE &					NO. 0938-039	
	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		· · · ·	TE SURVEY MPLETED	
	315290		B. WING		0	4/23/2021	
NAME OF PI	ME OF PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP COD	E		
BUCKINGHAM AT NORWOOD, THE				100 MCCLELLAN STREET NORWOOD, NJ 07648			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	I SHOULD BE	(X5) COMPLETIO DATE	
K 923	Continued From page	e 6	K 92	23			
	-	e outdoors in an enclosure or terior space of non- or					
	limited- combustible of	construction, with door (or					
		can be secured. Oxidizing					
	gases are not stored with flammables, and are separated from combustibles by 20 feet (5 feet if						
	sprinklered) or enclos						
	noncombustible construction having a minimum						
	1/2 hr. fire protection	•					
	Less than or equal to 300 cubic feet In a single smoke compartment, individual						
		r immediate use in patient					
		gregate volume of less than					
		feet are not required to be					
	stored in an enclosur	-					
		ions as specified in 11.6.2.					
		readable from 5 feet is on					
		a cylinder storage room,					
	where the sign includ	es the wording as a :: OXIDIZING GAS(ES)					
	STORED WITHIN NO						
		o cylinders are used in order					
		eived from the supplier.					
	Empty cylinders are s						
	-	lity employs cylinders with					
		ge, a threshold pressure					
		established. Empty cylinders					
	in the open are prote	confusion. Cylinders stored					
		, 11.3.4, 11.6.5 (NFPA 99)					
		is not met as evidenced					
	by:						
		n and interview, it was		HOW THE CORRECTIVE AC	CTION WILL		
		acility failed to comply with		BE ACCOMPLISHED			
		age requirements of NFPA			aubia fa at		
	99 as evidenced by t	ne ioliowing:		Oxygen tanks exceeding 300 were stored within 5 feet of co			
					กามนอแมเช		
	Oxygen tanks exceed	ding 300 cubic feet in volume		items.			

Facility ID: NJ60232

If continuation sheet Page 7 of 8

		MEDICAID SERVICES	יסיד וו וא (۲۵)	E CONSTRUCTION	OMB NO. 0938-039 (X3) DATE SURVEY	
	ID PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING		COMPLETED	
		315290	5290 B. WING		04/23/2021	
NAME OF P	ROVIDER OR SUPPLIER		:	STREET ADDRESS, CITY, STATE, ZIP CODE		
BUCKINGHAM AT NORWOOD, THE				100 MCCLELLAN STREET NORWOOD, NJ 07648		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE COMPLETION	
K 923	combustible items. A observed, in the press Maintenance Director (e-tanks) stored within items in a multi-suppl the basement of the k items were assorted p in three cardboard boo mattresses. The total this room was 625 cu exceeding the maxim feet in volume (12 e-t e-tanks was unsecure top of the other 24 e-t secured. This finding Maintenance Director observation.	At 12:00 PM the surveyor ence of the facility's r, 25 oxygen cylinders n 4-feet of combustible y storage room located in puilding. The combustible patient care supplies stored oxes and two bed volume of oxygen stored in bic feet in volume, um allowed by 325 cubic anks). Also, one of the ed and laying horizontally on tanks which were properly y was verified by the facility's in an interview during the	К 923		om any n n was ore and conduct storage are e ne	

Facility ID: NJ60232

If continuation sheet Page 8 of 8