PRINTED: 04/03/2023 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF	PLE CONSTRUCTION G 01	(X3) DATE SURVEY COMPLETED	
		315357	B. WING		01/20/2023	
	ROVIDER OR SUPPLIER	/E		STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	DATE	
K 000	New Jersey Departme Survey and Field Ope 1/18/2923 and 1/19/2 Cedar Grove was fou	023 and Alaris Health at nd to be in noncompliance	K 00	00		
	Safety from Fire, and Protection Association Code (LSC), Chapter Occupancies. Alaris Health at Ceda Type II Un-Protected	for participation in 42 CFR 483.90(a), Life the 2012 Edition of the Fire in (NFPA) 101, Life Safety 19 EXISTING Health Care r Grove is a Single-story, building that was built in incility is divided into 9 smoke				
K 271 SS=E	provides a level walki provisions of 7.1.7 wit elevation and shall be obstructions. Addition be a hard packed all- 18.2.7, 19.2.7	nged in accordance with 7.7, ng surface meeting the h respect to changes in maintained free of ally, the exit discharge shall weather travel surface.	K 27	71	2/23/23	
AROPATORY	Based on observation provided documentation of 1/18/2023, it was defailed 1) To provide 1 of 15 stable, hard packed a and maintain a level wobstructions and impension.	n and review of facility on on 01/17/2023 and termined that the facility exit discharges with a II-weather travel surface valking surface, free of all ediments to reach a public		The Exit from the basemen stairwell was paved with a stable, hard packed all -weather surface that was attached to an existing public walkway exiting away from the facility. The courtyard gate has a magnet lock to keep it lock and secure constar and a mechanical latch which was	tic	

Electronically Signed 02/13/2023

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MUL ⁻ A. BUILDI		CONSTRUCTION 1		(X3) DATE SURVEY COMPLETED	
		315357	B. WING	B. WING			01/20/2023	
	ROVIDER OR SUPPLIER	VE	•	STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009				
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE	
K 271	Continued From page	e 1	K	271				
	way (street or parking other emergency 2) To provide unobst accordance with Nati Association (NFPA) 19.2, 19.2.1, 19.2.7, 7.1.6.2, 7.1.6.3, 7.1.1 This deficient practice following: On 01/17/2023 during approximately 9:27 Athe Regional Director Director of Maintenar of the facility lay-out rooms and smoke concompany of the facility single story building with the RDN Along the two day too observed the following: 1) On 01/17/2023 at during a tour of the bobserved outside of a door (illuminated exit there was no level way way. The surveyor observer un of unleveled grass There was no clear a reach a public way.	g lot) in the case of fire or tructed exit discharges in onal Fire Protection 101, 2012 Edition, Section 7.7, 7.7.1, 7.7.3.2, 7.1.6, 10, 7.1.10.1. The was evidence by the survey entrance at the arguest was made to ref Maintenance (RDM) and the process of Maintenance (R			removed and a swipe card was installed for a one action means of exit. All residents have the potential to be affected. The Maintenance Director will make monthly rounds to ensure all exit discharges have a stable, all weather travel surface that leads to a public walkway without obstruction for the nemonths. The Maintenance Director will make monthly rounds on the courtyard gate to ensure the gate is locked and working properly for the next 6 months. The Maintenance Director will report the results of these audits to the Administron a monthly basis. The Maintenance Director will review the findings of the monthly audits at the Quarterly QAPI Meeting for the next 2 quarters.	xt 6		

PRINTED: 04/03/2023 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		CONSTRUCTION 1	(X3) DATE SURVEY COMPLETED	
		315357	B. WING_			01/	20/2023
	ROVIDER OR SUPPLIER EALTH AT CEDAR GROV	/E		1	TREET ADDRESS, CITY, STATE, ZIP CODE 10 GROVE AVE CEDAR GROVE, NJ 07009		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 271	that the gate was lock There was no keypad gate to unlock the gat emergency other ther Reference: New Jers Code 5:23: International Building 1. Section 1002 Defin "A continuous and un- and horizontal egress portion of a building of A means of egress co	rtyard the surveyor observed ked with a magnetic lock. I on the egress side of the se in the event of an a fire alarm activation. The ey Uniform Construction	K	271			
	times of observations The Administrator was at the survey exit on 0 1:15 PM. Fire Safety Hazard. NJAC 8:39-31.1(e) NFPA 101:2012 - 7.7 NFPA 101:2012- 19.2 Requirements Exit Signage CFR(s): NFPA 101 Exit Signage 2012 EXISTING Exit and directional si accordance with 7.10 also served by the em 19.2.10.1	s informed of the deficiency 01/19/2023 at approximately Means of Egress	Κź	293			2/23/23

AND PLAN OF CORRECTION	1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDIN	IPLE CONST IG 01	RUCTION	(X3) DATE SURVEY COMPLETED	
	315357	B. WING _			01/	20/2023
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE			STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009			
PREFIX (EACH DEFICIENCY M	MENT OF DEFICIENCIES IUST BE PRECEDED BY FULL DIDENTIFYING INFORMATION)	ID PREFIX TAG	(PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
travel is obvious.) This REQUIREMENT is by: Based on observation a provided documentation 01/18/2023 in the prese management, it was det failed to: 1) Maintain 2 signs observed in prope To provide 2 illuminated identify the exit access provided discharge door. This deficient practice we following: Reference: NFPA. Life Safety Code Access. Access to exits approved, readily visible the exit or way to reach apparent to the occupant NFPA Life Safety Code Continuous Illumination. Every sign required to b 7.10.7, and 7.10.8.1 sha illuminated as required to section 7.8, unless othe 7.10.5.2.2 Reference: New Jersey Code 5:23: International Building Code Signs of the portion of a building or section of a building or se	ants where the line of exit is not met as evidenced and review of facility in on 01/17/2023 and ince of facility itermined that the facility of 35 illuminated exit is working condition, 2) exit signs to clearly path to reach an exit was evidenced by the 2012 7.10.1.5.1 Exit is shall be marked by ite signs in all cases where the exit is not readily ints. 2012 7.10.5.2.1 The illuminated by 7.10.6.3, all be continuously under the provisions of rwise provided in To Uniform Construction ode, ons, Means of egress: structed path of vertical	К2	The "wes illum A ne the control into illum A near the control illum A near the montrol illum A near the montrol illum A near the montrol illum A near the findi A near the findi Qua	e illuminated Exit Sign located on the st" unit was replaced with a new ninated exit sign. Ew illuminated exit sign was added Wing corridor near the Kitche illuminated Exit Sign located above corridor double smoke doors leading the wing was replaced with a new ninated exit sign. Ew illuminated exit sign was added corridor exiting the Dinning Room or the Kitchen. Besidents have the potential to be cated. Maintenance Director will make nithly rounds to ensure all illuminates signs are in working order on a nithly basis. Maintenance Director will report the lits of these audits to the Administration monthly basis. Maintenance Director will review the monthly basis at the interly QAPI Meeting for the next 2 orters.	to n. e ng to ad	

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTII A. BUILDIN	PLE CONSTRUCTION G 01	, ,	(X3) DATE SURVEY COMPLETED	
		315357	B. WING		0	1/20/2023	
	ROVIDER OR SUPPLIER	/E		STREET ADDRESS, CITY, STATE, ZIP COD 110 GROVE AVE CEDAR GROVE, NJ 07009			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE	
K 293	discharge." 2. Section 1011, Exi required. Exits and e marked by an approv from any direction of exits shall be marked in cases where the extravel is not immediat Exit sign placement san exit access corridulisted viewing distanceless, from the nearest On 01/17/2023 durin approximately 9:27 Athe Regional Director Director of Maintenar of the facility lay-out vrooms and smoke confacility have a basem. The DOM told the surbasement and providilay-out. A review of the facility that the building is a surprise units (Exit and Continued on building with the RDM Along the two day tou observed 2 of 35 illunt functioning properly as	t signs: "1011.1 Where xit access doors shall be ed exit sign readily visible egress travel. Access to by readily visible exit signs xit or the path of egress ely visible to the occupants. hall be such that no point in or is more than 100 feet or e for the sign, whichever is at visible exit sign." If the survey entrance at M a request was made to of Maintenance (RDM) and ace (DOM) to provide a copy which identifies the various entrance at more than 100 feet or the sign, whichever is a led a copy of the facility of provided lay-out identified single story building with with and late (Incompared to the facility that are facility the surveyor innated exit signs not and two (2) locations that for the exit access path to	K 29	93			

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		CONSTRUCTION 1	(X3) DATE SURVEY COMPLETED	
		315357	B. WING _			01/20/2023	
	ROVIDER OR SUPPLIER EALTH AT CEDAR GROV	/E		1	TREET ADDRESS, CITY, STATE, ZIP CODE 10 GROVE AVE CEDAR GROVE, NJ 07009		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	X	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 293	1) On 01/18/2023 at observed one illuminated. 2) On 01/18/2023 at observed no evidence in the corridor leaving into the wing corridor double smoked wing was not illuminated. 3) On 01/18/2023 at observed one illuminated. 4) On 01/18/2023 at observed no evidence in the corridor double smoked wing was not illuminated. 4) On 01/18/2023 at observed no evidence in the corridor leaving into the wing. The RMD and DOM of times of observations. The Administrator was at the survey exit on 01:15 PM. Fire Safety Hazard. NFPA Life Safety Cook NFPA 101:2012- 19.2 Requirements NJAC 8:39 -31.1 and NFPA Life Safety Cook	ated exit sign above the door that was not 11:27 AM, the surveyor of an illuminated exit sign the Resident dining room porridor near the Kitchen. 12:51 PM, the surveyor ated exit sign above the endors leading into the luminated. 1:28 PM, the surveyor of an illuminated exit sign above the endors leading into the luminated. 1:28 PM, the surveyor of an illuminated exit sign at the Resident dining room corridor near the Kitchen. 1:29 PM, the surveyor of an illuminated exit sign at the Resident dining room corridor near the Kitchen. 1:20 PM, the surveyor of an illuminated exit sign at the Resident dining room corridor near the Kitchen. 1:20 PM, the surveyor of an illuminated exit sign at the Resident dining room corridor near the Kitchen. 1:21 PM, the surveyor of an illuminated exit sign at the Resident dining room corridor near the Kitchen.		293			
K 321 SS=E	Hazardous Areas - Er CFR(s): NFPA 101		K	321			2/23/23
		nclosure protected by a fire barrier istance rating (with 3/4 hour					

OLIVILIY	O I OIT MEDIO/IITE A	MEDIO/ ND GENTIOEG				CIVID IVC	7. 0000 000 I
	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		CONSTRUCTION 1	(X3) DATE SURVEY COMPLETED	
		315357	B. WING			01/	20/2023
	ROVIDER OR SUPPLIER EALTH AT CEDAR GRO	VE		STREET ADDRESS, CITY, STATE, ZIP COE 110 GROVE AVE CEDAR GROVE, NJ 07009			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
K 321	system in accordance When the approved a system option is used separated from other partitions and doors i Doors shall be self-cla and permitted to have protective plates that from the bottom of the Describe the floor and hazardous areas that 19.3.2.1, 19.3.5.9 Area Separation N/A a. Boiler and Fuel-Fir b. Laundries (larger that c. Repair, Maintenand d. Soiled Linen Room e. Trash Collection R (exceeding 64 gallons f. Combustible Storag (over 50 square feet) g. Laboratories (if cla Hazard - see K322) This REQUIREMENT by: Based on observation 1/18/2023 in the pres management, it was failed to ensure that f areas were self-closir smoke resisting partit NFPA 101, 2012 Edit 19.3.2.1.3, 19.3.2.1.5 8.3.5.1, 8.4, 8.5.6.2 a	a automatic fire extinguishing with 8.7.1 or 19.3.5.9. automatic fire extinguishing d, the areas shall be spaces by smoke resisting in accordance with 8.4. osing or automatic-closing enonrated or field-applied do not exceed 48 inches e door. It is a consider a consideration of the area deficient in REMARKS. Automatic Sprinkler and Paint Shops is (exceeding 64 gallons) osoms in an 100 square feet) ose, and Paint Shops is (exceeding 64 gallons) osoms in a consideration of facility determined that the facility determined that the facility determined that the facility irre-rated doors to hazardous ing, and were separated by the consideration, Section 19.3.2.1, in 19.3.6.3.5, 19.3.6.4, 8.3, in 19.3.6.3.5, 19.3.6.4, 8.3, in 19.	K	321	The supply storage door was fitted wit an automatic door closure located near the Physical Therapy room. The Medical Records room was fitted was an automatic door closure located near the Assistant Director of Nursing office. The Central Supply room was fitted wit an automatic door closure located near the Salon on the Unit. All residents have the potential to be	r vith r h	

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	LE CONSTRUCTION 01	COMPLETED
		315357	B. WING		01/20/2023
	NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE			STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009	1 0 1/20/2020
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC' (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRI DEFICIENCY)	JLD BE COMPLETION
K 321	approximately 9:27 Athe Regional Director Director of Maintena of the facility lay-out rooms and smoke coa review of the facility that the building is a units the facility. Starting on 01/17/20 AM and continued or building with the RD Along the two day to observed the following failed to have smoked as Physical Therapy are rooms automatic doo it had been removed The surveyor observe paper files and boxed recorded the room to feet) which is larger 2) On 1/18/2023 at inspection of the Me Assistant Director of performed. During a closure testinto the Medical Recorded not self-close. To	ang the survey entrance at AM a request was made to or of Maintenance (RDM) and nce (DOM) to provide a copy which identifies the various empartments. It is provided lay-out identified single story building with with units) in which was performed. It is a surveyor not the facility the surveyor not the facility the surveyor not hazardous areas that it is resisting doors, approximately 11:58 AM, an	K 32	The Maintenance Director will make monthly rounds to ensure all fire radoors to hazardous areas are equiwith self-closing doors and are in vorder. The Maintenance Director will reported results of these audits to the Admin on a monthly basis. The Maintenance Director will revisionings of the monthly audits at the Quarterly QAPI Meeting for the net quarters.	ort the histrator wew the

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
		315357	B. WING _			01/20/2023	
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE		/E			STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 321	boxes filled with comb cabinets filled with file paper files and 6 large filled with medical recomb and the Central supply rown was performed. The corridor door leading means to self-close. The surveyor observed combustibule boxes at 50 square feet. With these corridor dowould allow fire, smooth	ed in the room 12 large coustibule files, 8 filing es, 17 milk crates filled with e racks ords. 11:36 AM, an inspection of om, located near the Salon surveyor observed that the into the supply room had no	K	321			
K 351 SS=F	times of observations The Administrator was at the survey exit on 0 1:15 PM. NJAC 8:39-31.2 (e) Life Safety Code 101 Sprinkler System - Ins CFR(s): NFPA 101 Spinkler System - Ins 2012 EXISTING Nursing homes, and homes, are approved automatics	s informed of the deficiency 01/19/2023 at approximately stallation tallation hospitals where required by protected throughout by an prinkler system in A 13, Standard for the	K	351			2/23/23

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL ⁻ A. BUILDI		CONSTRUCTION 1	(X3) DATE SURVEY COMPLETED	
		315357	B. WING			01/20/2023	
	ROVIDER OR SUPPLIER EALTH AT CEDAR GRO	VE		1	TREET ADDRESS, CITY, STATE, ZIP CODE 10 GROVE AVE EDAR GROVE, NJ 07009		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 351	measures are permit sprinkler protection in or local regulations p In hospitals, sprinkler closets of patient slee of the closet does no sprinkler coverage or required by NFPA 13 Sprinkler Systems. 19.3.5.1, 19.3.5.2, 19.4.2, 19.3.5.10, 9.7 This REQUIREMENT by: Based on observation 1/17/2023 and 01/18 the Facility failed to in by CMS regulation senvironment to all arrequirements of NFP 19.3.5.1, 9.7, 9.7.1.1 Association (NFPA) Systems 2012 Edition New Jersey Uniform 5:23, for use group I-occupancy. The deficient practice following, On 01/17/2023 during approximately 9:27 A the Regional Director of Maintenar of the facility lay-out rooms and smoke confacility have a basem The DOM told the sur	ruction, alternative protection ted to be substituted for a specific areas where state rohibit sprinklers. It is are not required in clothes eping rooms where the area at exceed 6 square feet and overs the closet footprint as a standard for Installation of 19.3.5.3, 19.3.5.4, 19.3.5.5, 19.7.1.1(1) This is not met as evidenced on and interview on 19.3.5.3 it was determined that install sprinklers, as required 19.3.90(a) physical eas in accordance with the 19.3.1.5.1 in and National Fire Protection 19.3.1.5.1 in and as required by the 19.3.1.5.1 in and as required by the 19.3.1.5.5 in and 19.3.5.5 in and	K	351	Fire sprinklers were installed: Inside the stairwell (located next to the elevator) in the basement. Inside the basement level Medical Supstorage room. Inside the baeement's Main Electrical Room. Inside the Wing Attic Motor Accesarea. Inside the Wing Attic Motor Accesarea. All residents have the potential to be affected. The Maintenance Director will make monthly rounds to ensure all sprinkle heads are in place for the next 6 month. The Maintenance Director will report the results of these audits to the Administration a monthly basis. The Maintenance Director will review the findings of the monthly audits at the Quarterly QAPI Meeting for the next 2	ply s ess ess.	

	ND DLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDING	E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED
		315357	B. WING		01/20/2023
	NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE			STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009	1 01/20/2020
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPF DEFICIENCY)	ULD BE COMPLETION
K 351		e 10 by provided lay-out identified single story building with with and wings) in	K 35	l quarters.	
	AM and continued or of the RDM and DON conducted. Along the tour of the	ng locations that failed to			
	observed inside the selevator) leading to the evidence of fire spring At this time the surve				
	observed inside the supply storage room seven inch by seven	10:45 AM, the surveyor basement level Medical 's approximately four feet feet seven inch (4'-7" by no evidence of fire sprinkler			
	observed no evidence inside the approxiam	11:20 AM, the surveyor se of fire sprinkler coverage sately twenty three feet six x inch (23'-6" by 15'-6") Main			
		10:43 AM, the surveyor wing attic motor access			

NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION	20/2023
ALARIS HEALTH AT CEDAR GROVE 110 GROVE AVE CEDAR GROVE, NJ 07009	
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION	
	(X5) COMPLETION DATE
Continued From page 11 no evidence of fire sprinkler inside the 10' by 6' air handler area. 5) At approximately 1:44 PM, the surveyor observed inside the wing attic motor access (units wing attic motor access (units on evidence of fire sprinkler inside the 10' by 6' air handler area. The RMD and DOM confirmed the findings at the times of observations. The Administrator was informed of the deficiency at the survey exit on 01/19/2023 at approximately 1:15 PM. Fire Safety Hazard. NJAC 8:39-31.1(c), 31.2(e) NFPA 13. K 355 Portable Fire Extinguishers Portable Fire extinguishers are selected, installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers. 18.3.5.12, 19.3.5.12, NFPA 10 This REQUIREMENT is not met as evidenced by: Based on observations on 01/17/2023 and 01/18/2023 in the presence of facility management, it was determined that the facility failed to failed: 1) To inspect 5 of 38 portable fire extinguishers annually, 2). Install portable fire extinguishers annually, 2). Install portable fire extinguishers with-in the required by National Fire Protection Association as required by NFPA 101, 2012 Edition, Section 19.3.5.12, 9.7.4.1 and National Fire Protection Association (NFPA) 10. The 2 portable fire extinguishers swipe	2/23/23

PRINTED: 04/03/2023 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDII			(X3) DATE SURVEY COMPLETED	
		315357	B. WING		01/20/2023		
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE			STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009				
(X4) ID PREFIX TAG			ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE
K 355	for portable fire exting - 7.3 Maintenance 7.3 Maintenance 7.3.1.1 All Fire Extinonal Fire extination to maintenance at interpretation of the specifically indicated electronic notification. Reference #2 NFPA 1 - 6.1.3.8 Installation - 6.1.3.8.1 Fire extination weight not exceeding that the top of type fire than 5 feet above the - 6.1.3.8.3 In no case between the bottom of extinguisher and the first the inspection work of the person perform recorded at least more be kept on a tag or la extinguishers. During the building to 01/18/2023 in the precent Regional Director of Maintenant observed and inspect fire extinguishers in viollowing,	s 6.1, 6.1.3.8.1 and c. 5:70. 10 Edition 2010 Standard guishers reads, Inguishers shall be subjected ervals of not more than 1 ydrostatic test, or when by an inspection or 10 Height. Inguishers having a gross 40 lb shall be installed so the extinguisher is not more floor. In the hand portable fire floor be less than 4 inches. 10 4-3.4 At least monthly, the pass performed and the initials ing the inspection shall be atthly and that records shall the lattached to the fire the fire the floor of the fire the lattached to the fire the floor of the less than 4 inches.	K	355	lock on the an enclosed cabinets on Bhwere removed and a magnetic closure was replaced for all to access. All residents have the potential to be affected. The Maintenance Director will make monthly rounds to ensure all portable firextinguishers enclosed in a cabinet have magnetic locks, fire extinguishers are a regulatory height and have current inspected extinguishers that are working properly for the next 6 months. The Maintenance Director will report the results of these audits to the Administration a monthly basis. The Maintenance Director will review the findings of the monthly audits at the Quarterly QAPI Meeting for the next 2 quarters.	re /e t g e ator	

PRINTED: 04/03/2023 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		CONSTRUCTION 1	(X3) DATE SURVEY COMPLETED	
		315357	B. WING _	B. WING		01/20/2023	
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE			11	TREET ADDRESS, CITY, STATE, ZIP CODE 10 GROVE AVE EDAR GROVE, NJ 07009			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	REFIX (EACH CORRECTIVE ACTION SHOULD I			(X5) COMPLETION DATE
K 355	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Continued From page 13 locations had annual inspection tags dated 2021 that read, "Loaner" with no monthly punch or monthly visual examinations documented on the tags attached to the extinguishers. 2) One ABC type portable fire extinguisher located in the basement records storage area. This fire extinguisher appeared to be mounted too high. The surveyor measured and recorded the fire extinguisher was mounted at was mounted 5'-4" to the center of the pressure indicating needle. 3) One BC type portable fire extinguisher in the main electrical room appeared to be mounted too high. The surveyor measured and recorded the fire extinguisher was installed at a height of 5'-6" to the center of the pressure indicating needle. 4) Two portable fire extinguishers on the BHU unit were observed locked in cabinets in the corridor. At this time a request was made to the DOM can you open the cabinet. The DOM used his key swipe card to open and gain access to the extinguishers. The two extinguishers were only accessible to staff with knowledge and a swipe card. The RMD and DOM confirmed the findings at the times of observations. The Administrator was informed of the deficiency at the survey exit on 01/19/2023 at approximately 1:15 PM. NFPA 10		K	355			
K 361 SS=F	NJAC 8:39 -31.1 (c), Corridors - Areas Ope		K	361			2/23/23

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION G 01		(X3) DATE SURVEY COMPLETED	
315357		B. WING _	B. WING		1/20/2023		
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE				STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE	
K 361	treatment rooms and areas, nurse's station facilities, open to the with the criteria under 18.3.6.1, 19.3.6.1 This REQUIREMENT by: Based on observation interview on 01/17/20 presence of facility magnetic determined that the facility of the facility lay-out of the facili	en to Corridor atient sleeping rooms, hazardous areas), waiting s, gift shops, and cooking corridor are in accordance 18.3.6.1 and 19.3.6.1. It is not met as evidenced and record review and 23 and 01/18/2023 in the anagement, it was acility an open area to the corridor 500 square feet in A 101, 2012 Edition, Section 2012 Edition 19.3.6.1 (9) altipurpose therapeutic azardous areas, that are servision by facility staff shall en to the corridor provided	К3	The opening from the Dining If the corridor (leading to the) was sealed wi permanent wall. This opening will serve as an entry point into Area. All residents have the potential affected. The Maintenance Director will monthly rounds to ensure that remains closed. The Maintenance Director will results of these audits to the A on a monthly basis. The Maintenance Director will findings of the monthly audits a Quarterly QAPI Meeting for the quarters.	th a no longer to the Dining I to be make the corridor report the dministrator review the at the		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	PLE CONSTRUCTION G 01	(X3) DATE SURVEY COMPLETED		
		315357	B. WING		01/20/2023	
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE				STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009	,	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PROVIDER'S PLAN OF COI PREFIX (EACH CORRECTIVE ACTION TAG CROSS-REFERENCED TO THE DEFICIENCY)		OULD BE COMPLETION	
K 361	that the building is a units along with a Residen Main Entrance lobby center of the facility. Starting on 01/17/202 AM and continued or building with the RDM Along the two day to observed the following. 1. On 01/18/2023 at inside the resident diperformed. The dining approximately 5,000 approximately ten-for from the dining room the main entrance/ loshutter door that was At this time the surve was tied into the build that it will close with a larm. The RDM told the sunot connected to the The facility provided that was removed to into the corridor. The RMD and DOM times of observations. The Administrator was	y provided lay-out identified single story building with with and units) t Dining room, Kitchen and area with offices in the 23 at approximately 10:14 in 1/18/2023, a tour of the M and DOM was performed. Un of the facility the surveyor in 1/19, and 1/19	K 36			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 (X3) DA CC			(X3) DATE COMP	SURVEY LETED	
		315357	B. WING			01/20/2023		
NAME OF PROVIDER OR SUPPLIER ALARIS HEALTH AT CEDAR GROVE				STREET ADDRESS, CITY, STATE, ZIP CODE 110 GROVE AVE CEDAR GROVE, NJ 07009				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	PREFIX (EACH CORRECTIVE ACTION SHOUL		E ATE	(X5) COMPLETION DATE	
K 361	Continued From page NFPA 101 2012 edition Corridor Separation	e 16 on Life Safety Code 19.3.6.1	K	361				