DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/25/2020 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDING 0	ECONSTRUCTION 11	COMPLETED	
		315015	B. WING		10/07/2020	
NAME OF PROVIDER OR SUPPLIER MADISON CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 125 STATE HIGHWAY 34 MATAWAN, NJ 07747		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLETION	
E 000	Initial Comments		E 000			
K 000	This facility is in substantial compliance with Appendix Z-Emergency Preparedness for All Provider and Supplier Types Interpretive Guidance 483.73, Requirements for Long Term Care (LTC) Facilities. INITIAL COMMENTS		K 000			
	LIFE SAFETY CODE	: 101:2012 ubstantial compliance with				
	the Minimum Life Safety Code requirements as survey using CMS-2786R.					
K 324 SS=D	Cooking Facilities CFR(s): NFPA 101		K 324		10/30/20	
	with NFPA 96, Standa and Fire Protection of Operations, unless: * residential cooking of appliances such as motoasters) are used for cooking in accordance to cooking facilities operations with the conditions unfor * cooking facilities in some some such as a cooking facilities in some such as a cooking facilities protection of the some such as a cooking facilities protection of some such as a cooking facilities are some such as a cooking faciliti	equipment (i.e., small icrowaves, hot plates, food warming or limited e with 18.3.2.5.2, 19.3.2.5.2 en to the corridor in smoke of or fewer patients comply der 18.3.2.5.3, 19.3.2.5.3, smoke compartments with comply with conditions under ected according to NFPA equired to be enclosed as shall not be open to the				
I ABODATORY		12-2 GUPPLIER REPRESENTATIVE'S SIGNATUR	re .	TITLE	(X6) DATE	

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Electronically Signed

10/16/2020

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/25/2020 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 315015 B. WING 10/07/2020 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **625 STATE HIGHWAY 34 MADISON CENTER** MATAWAN, NJ 07747 (X5) COMPLETION DATE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX **PREFIX** REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 324 Continued From page 1 K 324 This REQUIREMENT is not met as evidenced bv: Based on observation and interview on 09/25/20 1. The grease baffles were adjusted to in the presence of the facility Maintenance be placed in the proper position to help Director and Regional Plant Operations Director, prevent flames and flammable debris it was determined that the facility failed to ensure from entering the exhaust duct. that 5 of 11 exhaust hood grease baffles were in the proper position to protect against grease and 2. All residents had the potential of being fire from entering above the exhaust hood affected by this deficient practice. system as per NFPA 96. 3. The grease baffles are currently in This deficient practice was evidenced by the working order but some are in need of following: replacement in the near future. The purchase of new grease baffles will be At 10:52 a.m., the surveyor observed 5 of 11 made to ensure that they are able to be exhaust hood grease baffles over the main installed correctly and their integrity is cooking area that had bent frames and not in the intact. intended positions leaving gaps at the following locations: 4. This will be reported at our monthly Left-side: QAPI. Maintenance director or designee will inspect the baffles weekly x 4 weeks, # 1 to # 2 (falling out of the track))over the then monthly x 2 months. We will convection oven reassess the frequency of inspecting #2 to #3 OK Right-side; #1 to #2 OK #2 to #3 OK #3 to #4 (2" gap) #4 to #5 (1" gap) #5 to #6 (2" gap) over the 6-burner cooking # 6 to # 7 (bent-frame 1" gap) #7 to #8 OK

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 11/25/2020 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI	PLE CONSTRUCTION G 01	(X3) DATE SURVEY COMPLETED		
		315015	B. WING _			10/07/2020	
NAME OF PI	ROVIDER OR SUPPLIER CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 625 STATE HIGHWAY 34 MATAWAN, NJ 07747			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE E APPROPRIATE	OULD BE COMPLETION	
K 324	(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		K 3.				